

Kasturi Solutions

B/204 Samrat Swastik Apt,
Opp Shankar Math
Solapur Road Hadapsar
Pune.

DATE:

To,
ARIHANT COLLEGE
PUNE

SERVICE REPORT

MODEL:

I have checked and found that the RO PLANT/WATER PURIFIER
Servicing and repairing has been completed to my satisfaction.

Checked & Verified -
Remark:

Customer Signature

Name *Sachin Ghorpale*

Mobile no *8888761990*

Date *04-03-2020*

for Kasturi Solutions



KONE Elevator India Private Limited
 Office No.4&9,Bandal Capital,81/1 Paud Road,
 Near Pmt Depot, Kothrud
 Pune-411038
 MAHARASHTRA
 Phone-020 - 25286962



INVOICE

TIN : 27520154280V
 PAN : AAACK2567P
 ServTax RegnNo. : AAACK2567PST001
 CIN : U29141TN1984FTC010913

BILLING ADDRESS

M/s ARIHANT EDUCATION FOUNDATION
 S NO.276/1,276/2,277/1,277/2
 BEHIND CRYSTAL HONDA SHOWROOM
 PUNE-411021
 MAHARASHTRA
 KIND ATTN MR SUHAS JOSHI
 PHONE-918805026904

CUSTOMER NAME & ADDRESS

M/s ARIHANT EDUCATION FOUNDATION
 S.NO.276/1,276/2,277/1,277/2
 BEHIND CRYSTAL HONDA SHOWROOM
 PUNE-411021
 MAHARASHTRA

Invoice No : 137722203
 Date : 02-JUN-2017
 Sales District : 28ZDM
 Business Area : V1

Cust TIN:
 Cust Serv Tax No:
 Sales Order No: 6370264
 Sales Order Date: 28-JUN-2016

Cust Code: 12182955
 Order No: KEI/0034/0005991928
 Order Date: 25-JUN-2016
 Cust PAN: AABTA6901F

SITE ADD ARIHANT EDUCATION FOUNDATION, S. NO. 276/1, 276/2, 277/1, 277/2, BAVDHAN BK.,
 BEHIND, PUNE, 411021, MAHARASHTRA

DESCRIPTION

Equipment No(s): 42778784 Network No & Description : 70639223 PWI08/10-19
 Gross Contract Value for Design, Manufacture, Supply, Installation, Testing and Commissioning of Elevator

QTY AMOUNT(INR)

1 1,360,000.00

RUPEES ONE MILLION THREE HUNDRED SIXTY THOUSAND ONLY

The above contract price is inclusive of all applicable taxes

Base Value

VAT LIABLE UNDER COMPOSITION / LUMP SUM SCHEME / EXEMPTION FEE

1,233,560.09
 98,684.81

Service Tax @14.00% on 15.00% of Base Value

25,904.76

Swachh Bharat Cess @0.50% on 15.00% of Base Value

Health Kalyan Cess @0.50% on 15.00% of Base Value

925.17

925.17

Kindly arrange to make your payment favouring "KONE Elevator India Private Limited".

TOTAL 1,360,000.00

Name of the Service : Works contract service

Note: Please release payment IMMEDIATELY on receipt of this invoice to avoid Interest @ 18% p a., kindly ignore if already paid

Bank Details: (Choose any one of below for remittance)

virtual Account# :	555512182955	555512182955
Current Account#	0520461027	42205015170.
Bank Name &	Citibank, N.A.	Standard Chartered Bank
Address	#163, Anna Salai, Chennai-600002	#19, Rajaji Salai, Chennai- 600001
IFSC	CITI0000003	SCBI0036076

For KONE Elevator India Private Limited

Signature valid

Signed By IYYAPPAN
 BALASUNDARAM
 KONE ELEVATOR INDIA (P) LTD
 Signing Date 05 JUN 2017

AUTHORISED SIGNATORY

Handwritten signature

Regd Office 60-55 & 58, Vanagaram Road, Ayanambakkam, Chennai-600095, Ph: 044-26533901/02/03/04
 Fax : 044-26533912, www.kone.com



A. B. GENSETS PVT. LTD.



Authorised Sales & Services Dealer of Cooper Gensets

Bhadawale Complex, Sr. No. 10, 1st Floor, Dhayari-Narhe Road, Near Kallias Jeevan Pune - 411 041.
 Tel No.: (020) 24690777 | Fax No.: (020) 24690255 Mobile: +91 9822758561 / 7447445066
 Email : abgppurchase@gmail.com | Website : www.abgensets.co.in

SERVICE REPORT

• CUSTOMER NAME & ADDRESS •

Date: 21/08/21

Arifant Education	Engine Model: GR1080TA	Sr. No.: 6H.3538/1001712
Collage Bavdhan	Alternator Model: K4224H	Sr. No.: 1253H0105105420
Pune	Alternator Make: KOEL	Rating: 125 KVA
	Application: Genset	Hours: 378

Contact Person: Poland sir Service Engineer Name: Ganesh mahite
 Contact No.: 9423468123 Contact No.: 7447445062

Nature of Work: Amc visit

• CHECK POINTS •	• OBSERVATIONS •	• CHECK POINTS •	• OBSERVATIONS •
Radiator Condition & Water Level	Level ok	Lub Oil Level	ok
Fan Bell's Tensions	Checked ok	Lub Oil Conditions	Good Level
HCT Switch	ok	Air Filter Conditions	ok
LLOP Switch	ok	Battery Conditions	ok
Rubber Hoses Tightness & Condition	ok	Battery Water Level	ok

PARAMETER READING	Voltage	Current	RPM	HZ	Oil Press	Oil Temp.	Water Temp.
	415	Amper	1500	51.2	5.1	Normal	Normal

Work Done: Above site Amc visit Work Done
 Engine oil Level check up Condition found ok
 Radiator coolant Level ok
 Battery Water Level ok
 engine Fan Belt Tension ok
 Dc set Ac And Dc proper checked ok
 Dc set manually tripped Done and working ok

Customer Remark:

Customer Seal & Signature

Service Representative Signature



ARIHANT COLLEGE OF A.C.S BAVDHAN




SERVICE REPORT: - office, staff room, washroom, Etc.

NO	DATE	SERVICE DETAILS	SIG. APC.	SIG. ACACS	REMARK
1	12/10/19	GPC & RC treatment	OK	OK	
2	12/10/19	Snake & Rat control (outside)	OK	OK	
3	22/10/19	4 th & 5 th Floor GPC & RC	OK	OK	
4	17/11/19	GPC & RC treatment	OK	OK	
5	14/12/19	GPC & RC treatment.	OK	OK	
6	20/1/20	GPC & RC treatment	OK	OK	
7	20/1/20	Snake & Rat control (outside)	OK	OK	
8	23/2/20	GPC & RC treatment	OK	OK	
9	10.10.20	GPC & RC treatment	OK	OK	
10	13.12.20	GPC & RC - 71 -	OK		
11	23.1.21	GPC & RC - 1 -	OK		
12	27.2.21	GPC & RC	OK		
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

PEST CONTROL Helpline- 7507277735, 9822297735, apenasik@gmail.com

ARIHANT COLLEGE

For AMIT PEST CONTROL



SERVICE REPORT

Report No.: 1465 Date: 4/9/2020

Customer Name: Arihant college

Address: Baner PUNE - Mumbai Road

Contact Person: Saehin Sir

Telephone: _____ Mobile: _____

Dt. of Call Received: 4/9/2020

Dt. of Call Attended: 4/9/2020 Time In: 11:30

Dt. of Call Completed: 4/9/2020 Time Out: 1:00

Type of System: Stability OES If Call Basis _____

Type of Service: Warranty AMC Call Service Charges _____

Engg. Name: Kishor Swamy Rs. _____

System Faults: New Extms connection

Action Taken: checked EPABX system & New Extms connection

Replaced New 20 pairs cable MDF Box cabling.

[Signature]
4.9.2020
Customer Sign.


Engg. Sign [Signature]

Company Seal:



Date:





ISO 9001-2015 CERTIFIED COMPANY

A. B. GENSETS PVT. LTD.

• Authorised Sales & Services Dealer of Cooper Gensets •



Bhadawale Complex, Sr. No.10, 1st Floor, Dhayari Narhe Road, Near Kailas Jeevan, Pune - 411 041.
Tel No. : (020) 24690777, Mob.: 9822758561 / 7447445066
Email : abgplpurchase@gmail.com | Website : www.abgensets.co.in

SERVICE REPORT

CUSTOMER NAME & ADD.:		Date:	02/07/21
Amihant education	Engine Model: 6P1080TA	Sr. No.:	6H3533/1001712
Hardham Pump	Alternator Model: 104224M	Sr. No.:	ES3405-104224
	Alternator Make: Pilsione	Rating:	17.5 KW
	Application: gensets	Hours:	396 hrs

Contact Person:	Service Engineer Name: Dnyaneshwar
Contact No.:	Contact No.: 7447495076

Nature of Work: Arc visit on check condition.

CHECK POINTS	OBSERVATIONS	CHECK POINTS	OBSERVATIONS
Radiator Condition & Water Level	TOP UP OK	Lub Oil Level	TOP UP OK
Fan Bell's Tensions	OK	Lub Oil Conditions	OK
HCT Switch	OK	Air Filter Conditions	OK
LLOP Switch	OK	Battery Conditions	Low Flatter water


Work Done: Engine lube oil level - TOP UP OK
 Engine coolant TOP UP - OK
 Engine Battery water - low and TOP UP
 Engine filter condition - OK
 Engine starts OK condition

Parameter Reading	Voltage	Current	RPM	HZ	Oil Press.	Oil Temp.	Water Temp.
	41.5	-	1500	501	4.7	-	40.1

Customer Remark:

Shankar
21/7/21
Customer Seal & Signature

Dnyaneshwar
Service Representative Signature



CUSTOMER DETAILS
 Customer Name: Arihant Education Foundation
 Full Address: Bardhan, pane.
 Pin Code: _____
 Mobile No.: _____
 Email Id: _____

PRODUCT DETAILS
 Model: Luminous CR 420514
 Serial No: 10KVA UPS 285835R1001899
 Status: Warranty Contract Billable
 Type of Call: Trouble PM Installation
 Power Audit Battery Test Others

Problem Reported: VPS Not working on Battery mode
 Reason for visit: _____

CALL SCHEDULE

Date	Time	Item Replaced	Part - 1	Part - 2
28.08.21	13:30	Old Sr. No.		
	16:30	New Sr. No.		
		Charges if any		

SITE OBSERVATION

Battery Reading during charging: Battery One Voltage: 2.06 Vdc, Battery Two Voltage: _____ Vdc

Battery Reading during Discharging: Battery One Voltage: 1.70 Vdc, Battery Two Voltage: _____ Vdc

Site Environment Detail: AC Provided: Yes No, DG Provided: Yes No, is environment Dusty: Yes No

Location where UPS installed: Computer Room Electrical Room Network Room Other (if any)

Battery Bank Description

Reading during Charging	Make: AuroBat	Ah: 200	Qty.: 15	Front Indication	Calibration Constant
2.06 Vdc	Reading during Discharging	1.70 Vdc		Operation during V/sit	Found
Batt 1	Batt 1	Batt 2	Batt 3	<input type="checkbox"/> On mains <input type="checkbox"/> On Battery	b =
Batt 2	Batt 4	Batt 5	Batt 6	<input type="checkbox"/> On Bypass <input type="checkbox"/> Dead	4 =
Batt 3	Batt 7	Batt 8	Batt 9	Load 60 %	5 =
Batt 4	Batt 10	Batt 11	Batt 12	Charge 70 %	6 =
Batt 5	Batt 13	Batt 14	Batt 15	Fault Code (forSURT)	0 =
Batt 6	Batt 16	Discharging Current		Battery Batch Code	

Feedback/Suggestion: Batteries weak needs to be replace UPS test ok. Checked UPS found in Bypass mode. Switch on line mode & test UPS found working o.k. mains & Battery all batteries are weak needs to be replace.

Customer Signature: Gopal palod
 Date: 28.8.21

Seal: _____

Signature: Jitendra Sunke

Date: 28.8.21

power, data centre, print, electric safety

EAT-N, APC by Schneider Electric, Schneider Electric, POWEReasy Safe India. Save India.

Contact : 7798880005 / 020-25457846/47
 email: service@powertechincs.co.in